




II. 18 (variations), livit of Afficial (C. 1804), In Christian (1800), Il kionized probability, Ir incompetit ets Allafetet, franz e fetta feta tetafététetat, les usaett e adandes constructions et assissants विकिर्णात्वस्थानिक निभुकाणांच निमस्स





### Conditions

The following conditions must be implemented within next 3 months as per standard - IX and standard - X given for the warehouse workshops of garments industries by Fire Service Rules - 1961 and S. R. O. No. 109 Act -99 published on 25th May, 11th of Jaishtha - 1406 under said rules.

- The godown/factory should be kept open for inspection at any time (after sunrise and before sunset) by the Director General of Fire Service and Directorate of Civil Defense officer/inspection team nominated by the authority authorized by the Director General.
- 2. No part of the godown or factory can be used as accommodation. The roof of the godown or factory can not be used for manufacturing materials fully or partially, for making or drying up or for storage.
- 3. Smoking, carrying of box of matches and lighter, pack of bidi & cigarette, uses of open lamp, uses of such light or lamp which sparks off are completely prohibited within the courtyard for loading and unloading goods and specified compound inside factory/godown.
- 4. Usages of electrification/provision of lighting should be ensured as per factory law inside godown/factory and provision of gangway for movement including installation of machine and storage of materials should be ensured as per the same law.
- 5. The organization must enforce and ensure the following provisions to ensure extinguishing and control outright probable fire accident to be occurred in the organization and the provision of fire prevention:

Seal & Signature of the Synatory here by AUTHENTESTED (Whole of Cana

Supra Contract of the



Administrative management of the representation of the rest of the

Assistant Translator

For Dhaka Translation





### bidli bigdin

অনুবাদ ও বিদেশ বলোও সভ্য কাছে কালাত সভ্য কাছে কালাত সভ্য কৰ্

translated Copy

(1) a) Weight riser and sprinkler must be installed in the building. Installation of minimum 1 riser point for each 4,500 Sqft. of area on each floor of the building and another riser point for excess floor area should be ensured. The riser point should be stored in the box by the side of it by fixing 100 feet long and variable nozzle/defuser nozzle having 1.5 dia to each riser point.

b) A sprinkler head should be installed for each 100 feet area inside godown/factory located in all floors of the building. The exact capacity of storage of hit of gas valve defusable cover of each sprinkler head should be 56°C. With it a fire service connection (female coupling) should be attached. The diameter of fire service connection will be 2.5". The pressure of water of riser pipe should minimum 2.5 bar and pressure of water of fire service connection should be 5 bar.

c) To pour the flow of water of riser and sprinkler underground reservoir of minimum 50,000 gallons should be installed including installation of ground floor/basement fire fighting pump house in the building. To ensure flow of water to the riser point and sprinkler from this pump house connection of flow of water to all risers and sprinkler should be ensured by installation of vertical pipe in the building. The flow of water of vertical pipe should be 7 bar. Installation of a main pump and a reservoir pump and a jockey pump should be ensured in fire fighting pump house. One of the pumps should be operated by diesel and another should be run by electricity. If two are electrically

run then alternative power connection must be ensured.







## जिल्हा छाड़ ताम

THE AND THE AND SEED OF THE AN

व्यक्तिसम्बद्धाः भवकातीः व्यक्तिक स्थानम् । व्यक्तिक स्थानम् । व्यक्तिक विश्वस्तानिकास

Translated Copy

(2) Installation of one photo-electric type smoke detector should be ensured for each 100 square feet of factory and godown.

(3) Sufficient number of automatic fire alarm bell along with call point should be installed outside the emergency exit stair case/main gate and corridor.



Installation of sufficient number (dual source) emergency light in the floor area of all the floors including installation of battery and electricity run (dual source) lighted exit signs on the exit access of emergency exit stair case and on the top of both the side of the door of each stair case of workshop/warehouse must be ensured.

- (5) Installation of at least one emergency exit staircase for each 25 meters should ensure. All ingredients of emergency exit staircase should be as per BNBC part 4.
  - To discharge smoke and heat expeditiously during fire vent should be installed inside the godown/factory, has alternatively there has to be sufficient number of exhaust fans should be installed. With these fans connection of electric line from standby generator should be ensured.
- (7) One fire extinguisher should be installed for 550 Sft. area of each floor. As per this estimate the number of 5/6 Kg capacity dry chemical ABC type extinguisher should be 70% and number of CO<sub>2</sub> extinguishing machine should be 30%. For all electric installations one ABC type and one 5/6 Kg CO<sub>2</sub> (Carbon-di-Oxide) fire extinguishing machines should be preserved for.





# bide oldan

প্রতি স্থান্তর গ্রাণ্ডরী জ্ গ্রোগ্ডা, সভ তি ভূকেন্ড্রন সভেক প্রক

Translated Copy

- (8) Workshop/warehouse gangway should be marked by bright colour.
- (9) Thunder prevention provision should be installed on the roof of the building. Electric earthling provision of the building must be well protected.





- Very combustible chemicals should be stored with tolerable heat control system in separate rooms. The fuel oil used in the factory should be store in safe place.
- 25% of the manpower among the officers and employees working should be imparted training on extinguishing fire, rescue and first aid from fire service and civil defense. Whole time fire fighting team should be formed by this trained manpower.
- (12) Upto next two years fire drill should be organized in cooperation with fire service and civil defense department each three months. And participation of all in the fire drill should be ensured.



- (13) PA system should be installed in the godown/factory and all rooms and all staircases and emergency exit staircase of the godown and factory should be brought under PA system. PA system should be controlled from fire command room.
- (14) The dust on the wall and roof of the building should be cleaned minimum once in a week.
- (15) Smoke store lobby should be made out side entrance of each floor of the existing two staircases and provision will have to be made so that three times pressure can be created on minimum per square inch inside the staircase automatically during fire inside the staircase for



Serginates, West Historial Card, Interestion dietest, interestation, in entining, that i spenjagging by the mell infanter and enterprise and amount

Translated Copy

अनुवाम ध विदाल विश्वकाना विश्वत সভৰ্ক থাকন

keeping the two staircases free from heat and smoke including installation of minimum one hour fire rated door on the two staircases like emergency exit staircase. Provision should be ensured to keep the landing area of the staircase free from fire flame and smoke.

- (16) One room adjacent to main gate of the building or security post of the building should be marked as fire command room and main panel board should be installed in this room and connection of all detectors and alarm bells installed in the building with the panel board should be ensured. In the fire command station the following equipments should be preserved for emergency used and presence of one operator on full time basis should be ensured.
- (17) If the height of the building is more than 5th floor or if it is high rise building and if the floor area is more than 500 square meters then installation of fire lift should be ensured in the building.

	- 1	١.
A 10		2.
70 60	3	3.
300	1/1/	4
为有温	e	7

01 (one) Main panel board

01 (one) set Control module of PA system

01 (one) Telephone set (minimum)

01 (one) Mobile set (minimum)

05 (five) Touch light

02 (two) sets Breathing apparatus 6.

Fire suit (Helmet, Gumboot, Hand globes & light) 05 (five) sets 7.

10 (ten) sets 8. Beater

02 (two) Fireman Axe 9.

01 (one) Stretcher 10.

01 (one) First aid box 11.

of 01 (one) numbers telephone Board containing 12. emergency services

Architecture plan of building

Seal & Signature of the anymatory have by

01 (one)

TRANSLATED BY

Assistant Translator

For Dhaka Translation